

Verified Inspection Report

Certified same-day inspection completed nationwide.

Order #C5A54D69 · Amanda Robinson · 5 PM CST



SCAN FOR FULL REPORT

View the full report online (photos & video) !'

UNIT OVERVIEW

YEAR

2020

MODEL

T680

STOCK NUMBER

ENGINE TYPE

Cummins X15

TRANSMISSION

Eaton Endurant 12-speed (AMT)

BODY COLOR

Grey

INTERIOR MATERIAL

Leather

NUMBER OF FUEL TANKS

2

ENGINE STARTS

Y

MAKE

Kenworth

VIN

1XKYD49X3LJ402029

MILEAGE / ODOMETER

593640

DRIVE TYPE

Tri-axle

AXLE SETUP

6.4

INTERIOR COLOR

Grey

GVWR

SLEEPER TYPE

Sleeper — raised roof

TOTAL FUEL CAPACITY (GAL)

100

1. POWERTRAIN, MECHANICAL & APU

1.1 Core Engine & Transmission Specs

ENGINE MAKE

Cummins

HORSEPOWER (HP)

400 hp

TRANSMISSION MAKE

Eaton Fuller

ODOMETER (MI)

593640

APU PRESENT

No

APU HOURS

ENGINE MODEL

Cummins X15

TORQUE (LB-FT)

1,650 lb-ft

TRANSMISSION TYPE

Automatic

ENGINE HOURS

25181

APU TYPE

None

IDLE RPM

1.2 Fluid Levels & Leak Inspections

● Engine Oil Level & Dipstick

PASS

● Engine Coolant & Leaks	PASS
● Transmission Fluid & Leaks	PASS
● Differential Leaks	PASS
● Brake Fluid & Lines Leaks	PASS
● Power Steering Fluid & Leaks	PASS

1.3 Under-Hood & Mechanical Systems

● Air Filter Condition	PASS
● Battery & Charging System	PASS
● Cooling Fan & Radiator	PASS
● Radiator Cap Sealing	PASS
● Belts & Hoses Condition	PASS
● Exhaust / Muffler System	PASS
● CV Joints & Axles	PASS
● Shocks & Bushings	PASS
● Ball Joints & Tie Rods	PASS
● Hydraulics System	PASS

2. EXTERIOR CONDITION & GLASS

2.1 Body Integrity & Paint

● Body Alignment	PASS
● Scratches, Dings & Dents Coupe cracks & scratches (Normal) see Pictures	ATTENTION
● Paint Condition & Rust	PASS
● Bumpers & Side Moldings	PASS
● Frame Damage Check	PASS

Notes: truck hook opens / closes a with extra effort. Could not record video due to single person. Refer to dealer. (not major)

2.2 Glass, Seals & Exterior Equipment

● Glass & Windshield	PASS
● Body Seals & Weatherstripping	PASS
● Wiper Blades & Washer System	PASS
● Door Mirrors & Backup Camera	PASS
● Special Equipment Catwalk Storage panels - 5x (works & opens)	PASS

3. CAB INTERIOR & AMENITIES

3.1 Controls, Electronics & Dashboard

● Steering Wheel & Horn	PASS
● Cruise Control System	N/A
● Clock, Radio & Navigation	PASS
● Power Locks & Switches	PASS
● Window Switches & Function	PASS
● Dash Lights & Gauges	PASS
● Key Fob Functionality	PASS
● Adaptive Driving Tech	N/A

3.2 Cabin Environment & Comfort Checks

● Seat Condition & Belts	PASS
● Inner Door Panels	PASS
● Center Console & Visors	PASS
● A/C, Heater & Defroster	PASS
● Blower Motor Function	PASS
● Carpet & Floor Mats	PASS
● Headliner & Trim Panels	PASS
● Cup Holders	PASS
● Inverter & Fridge	PASS
● Cigarette Use & Odors	PASS

Notes: All normal use - nothing broken

4. TITLE, LIEN & WARRANTY CHECKS

4.1 Title & Ownership

● Lien Check	N/A
● Accident History Check	N/A

4.2 Coverage & Warranty

● Factory Warranty	N/A
● Aftermarket Warranty	N/A

5. TIRE CONDITION & INDIVIDUAL TREAD DEPTHS

5.1 Individual Position Tread Depths

● Front Left (Steer) (Left steer)	PASS · 11/32
● Front Right (Steer) (Right steer)	PASS · 11/32
● Rear Left Outer (Left outside drive front)	PASS · 11/32
● Rear Left Inner (Left inside drive front)	PASS · 11/32
● Rear Right Outer (Right outside drive front)	PASS · 11/32
● Rear Right Inner (Right inside drive front)	PASS · 11/32

5.2 Wear Pattern Analysis

● Uneven / Irregular Wear	PASS
---------------------------	------

New tires

6. ROAD TEST & PERFORMANCE

6.1 Operational Performance Checks

● Engine Performance	PASS
Drove truck inside the dealership lot.	
● Transmission Performance	PASS
Drove truck inside the dealership lot.	
● Braking Performance	PASS
Drove truck inside the dealership lot.	
● Differential Performance	PASS
Drove truck inside the dealership lot.	

6.2 Ride, Handling & Dash Alerts

● Suspension Performance	PASS
Drove truck inside the dealership lot.	
● Wheel Bearing Performance	PASS
Drove truck inside the dealership lot.	
● Steering Performance / Wander	PASS
Drove truck inside the dealership lot.	

- **Active Warning Lamps**

PASS

Check fault codes

7. LIGHTING & FLASHERS VERIFICATION

7.1 Front Lighting

- **Daytime Running Lights**

PASS

- **Headlights (High / Low Flash)**

PASS

- **Front Turn Signals**

PASS

7.2 Rear Lighting & Flashers

- **4-Way Hazards / Flashers**

PASS

- **Rear Lights (Brake, Reverse, Signal)**

PASS



- **Reverse Alarm**


PASS

PHOTOS (124)


Exterior Photos










Interior Photos























Engine Bay Photos

















Stickers & Plates










Tires, Axles, Suspension & Brakes























ECM Reports & Live Data





Documents






VEHICLE

Engine Total Idle Hours 14933 h

Engine Total Idle Fuel Used 10553 gallons

Engine Total Hours of Operation 25181 h



VIDEOS (5)

Video cannot play inside a PDF — open the online report to watch these clips.

- **Video 1 — Videos**
- **Video 2 — Videos**
- **Video 3 — Videos**
- **Video 4 — Videos**
- **Video 5 — Videos**